



Remarks:

18.08.01 The layout error: the "place outline" areas of XP2, XP4 and XP6 connectors overlap (they don't fit together).

06.06.06 The signals TRES and TRH were swapped to use the latter to control the raw data transmission. The old TRH path was damaged by radiation.

H.Henschel, I.Tsurin		
Title		
Front panel input connector and differential receivers for trigger signals		
Size	Document Number	Rev
	BST Pad trigger system: Repeater card	0
Date:	Tuesday, June 06, 2006	Sheet 1 of 7