



P50V >>
 N50V >>
 P33V >>

M3
 2.5 mm
 XP3
 M20-9990205

XS2
 3M-IDC-50

XP4
 ITW-057-40S

M4
 2.5 mm

R18
 1K

Remarks:
 18.08.01 The layout error: the "place outline" areas of XP2, XM4 and XP6 connectors overlap (they don't fit together).
 06.06.06 The signals TRES and TRH were swapped to use the latter to control the raw data transmission. The old TRH path was damaged by radiation.

H.Henschel, I.Tsurin		
Title Front panel input connector and differential receivers for trigger signals		
Size	Document Number BST Pad trigger system: Repeater card	Rev 0
Date:	Tuesday, June 06, 2006	Sheet 2 of 7