



ALTERA

EP1K30TC144

Remarks:

18.08.01 The layout error: the capacitor C16 is inside the "place outline" area of the U13.

H.Henschel, I.Tsurin		
Title		
Synchronization and delay supervisor for control signals		
Size	Document Number	Rev
	BST Pad trigger system: Repeater card	0
Date:	Tuesday, June 06, 2006	Sheet 4 of 7