



Remarks:

18.08.01 The layout error: the "place outline" areas of XP13, XP14 and XP15 connectors overlap (they don't fit together).

H.Henschel, I.Tsurin		
Title Piggyback input connectors and strobe drivers		
Size	Document Number BST Pad trigger system: Repeater card	Rev 0
Date:	Friday, September 23, 2005	Sheet 1 of 5