# How to migrate from Windows 7 to Windows 10 using Particulars PSTCT and Standa 8SMC controller!

1.) Download the package from here (or Standa)
2.) Unizip it in any folder of your liking
3.) Run SMCView on Windows 7 machine and update the firmware according to instructions in the readme_firmware_update.txt .
4.) Install the MicroSMC (installing MicroSMCx64 will not make your stages ready for PSTCT)!
5.) Restart the machine with driver signing disabled;  hold SHIFT while restarting the computer select "Troubleshoot" , "Restart"  and then F7 (disable driver signature enforcement)
6.) Run "Device manager" and under unknown device select driver manually in the folder where you installed SMCView in the Drivers folder. Select "8SMC1-USB(h)" and ignore windows warning. You should the drivers under NI-VISA USB Devices. Having any other configuration (MicroSMCx64.sys driver) will not work.



7.) That's it.