
IRRADIATION 2009 MOTOR CONTROLLER AND TEMPERATURE MONITOR
ATTENTION!
220V
RS 348-431 SSRLY
CON7
CON8
HDR5
HDR10
HDR15
HDR20
HDR25
HDR30
HDR40
HDR50
Motor LIMIT SWITCHES
Motor sensing
INSERT JUMPERS FOR 2 WIRE OPERATION
SENSE
SOURCE