



HT to detector

There is an error on the prototype hybrid = c114 abd 115 should be connected to ground and not to the HT return. This will not cause any problem if R23 is a zero ohm link(default)

1	UCC	2	UCC
3	UCC	4	UCC
5	RNM15-3	6	RNM15-3
7	RNM15-2	8	RNM15-2
9	GND	10	GND
11	RNM15-1	12	RNM15-1
13	RNM15-8	14	RNM15-8
15	GND	16	GND
17	RNM14-3	18	RNM14-3
19	RNM14-2	20	RNM14-2
21	GND	22	GND
23	RNM14-1	24	RNM14-1
25	RNM14-8	26	RNM14-8
27	GND	28	GND
29	HIRET	30	HIRET
31	remove	32	remove
33	remove	34	remove
35	remove	36	remove
37	remove	38	remove
39	remove	40	remove
41	remove	42	remove
43	remove	44	remove
45	NC	46	NC
47	RNM13-3	48	RNM13-3
49	RNM13-2	50	RNM13-2
51	GND	52	GND
53	RNM13-1	54	RNM13-1
55	RNM13-8	56	RNM13-8
57	GND	58	GND
59	RNM12-3	60	RNM12-3
61	RNM12-2	62	RNM12-2
63	GND	64	GND
65	RNM12-1	66	RNM12-1
67	RNM12-8	68	RNM12-8
69	GND	70	GND
71		72	
73	RNM11-3	74	RNM11-3
75	GND	76	GND
77	RNM11-2	78	RNM11-2
79	RNM11-1	80	RNM11-1
81	GND	82	GND
83	RNM11-8	84	RNM11-8
85	RNM11-3	86	RNM11-3
87	GND	88	GND
89	RNM11-2	90	RNM11-2
91	RNM11-1	92	RNM11-1
93	GND	94	GND
95	RNM11-8	96	RNM11-8
97	ENDEC	98	ENDEC
99	GND	100	GND
101	DRUN	102	DRUN