



Remarks:

18.08.01 Resistors R112 and R113 and the diode VD6 are not in the actual layout.

18.08.01 The layout error: resistors R58 and R62 are inside the "place outline" area of the XP8.

H.Henschel, I.Tsurin		
Title Auxiliary circuits		
Size	Document Number	Rev 1
BST Pad trigger system: Repeater card		
Date: Friday, September 23, 2005	Sheet 5	of 7